





9 A




9 B



9 C



9 D



9 E

- Figure 9A. Thermal imagery showing icing near Globe Creek Crossing
- Figure 9B. Oblique photograph made in June 1974 showing residual ice.
- Figure 9C. Frame photograph of area surrounding site.
- Figure 9D. Example of strip photography with too much uncompensated roll — be useful for interpretation.
- Figure 9E. Livengood 1-3 topographic map.